



**Test Report TR S2510PoE-DC**  
*Firmware Version build 71585*

## **Contents**

<b>1. Introduction</b>	<b>3</b>
<b>2. About This Test Report</b>	<b>4</b>
<b>3. Test Report</b>	
<b>A. RJIL-IP-QA-DS-SYS-026</b>	<b>5</b>



## **1. Introduction**

**This document is known for problems and solutions for  
TECHROUTES TR S2510PoE-DC Series switch.**

## **2. About This Test Report**

**This Test Report provides information for**

**A. To check have proper POST (POWER ON SELF TEST ) procedures.**

**Present software version- Version 2.2.0C Build 71585;**

**Present hardware version- V1.0;**



### 3. Test Report

#### A. RJIL-IP-QA-DS-SYS-026

1 . To check have proper POST (POWER ON SELF TEST ) procedures.

#### 2. Test Set up : Switch





### 3. Procedure:

1. Give reboot to the switch and then we will see the below booting sequence

Switch# reboot

Do you want to reboot the Switch(y/n)?y

System Bootstrap, Version 0.3.8, Serial No:20022012997

Techroutes Network Pvt. Ltd

Techroutes TR S2510POE-DC

Current time: 1970-1-1 0:00:00

SDRAM Fast Test.....PASS!

Flash Fast Test.....PASS!

RTC Test.....PASS!

Loading Switch.bin.....

Start Decompress Switch.bin

